

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION DIXON UNIFIED SCHOOL DISTRICT		COUNTY SOLANO	
SCHOOL SITE SILVEYVILLE CHARTER SCHOOL		SCHOOL TYPE (GRADE LEVELS) K THRU 8	NUMBER OF CLASSROOMS ON SITE 35
INSPECTOR'S NAME JOSEPH C. LUIS	INSPECTOR'S TITLE CSI - CONSULTANT	NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE)	
TIME OF INSPECTION 9:25AM	WEATHER CONDITION AT TIME OF INSPECTION SUNNY		

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

TOTAL NUMBER OF AREAS EVALUATED	CATEGORY TOTALS	A. SYSTEMS			B. INTERIOR	C. CLEANLINESS		D. ELECTRICAL	E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL	
		GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/TERMITE INFESTATION	ELECTRICAL	RESTROOMS	SINKS/FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/SCHOOL GROUNDS	WINDOWS/DOORS/GATES/FENCES
↓ 63	Number of "OK"s:	63	57	63	29	62	63	40	14	35	59	53	52	51	57	54
	Number of "D"s:	0	2	0	30	1	0	19	1	13	0	10	7	8	6	9
	Number of "X"s:	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	Number of N/A's:	0	4	0	4	0	0	4	48	15	4	0	4	4	0	0
Percent of System in Good Repair Number of "OK"s divided by (Total Areas - "NA"s)*		100.00%	96.61%	100.00%	49.15%	98.41%	100.00%	67.80%	93.33%	72.92%	100.00%	84.13%	88.14%	86.44%	90.48%	85.71%
Total Percent per Category (average of above)*		98.87%			49.15%	99.21%		67.80%	83.13%		92.07%		87.29%		88.10%	
Rank (Circle one) GOOD = 90%-100% FAIR = 75%-89.99% POOR = 0%-74.99%		GOOD			POOR	GOOD		POOR	FAIR		GOOD		FAIR		FAIR	

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING:	DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE →	83.20%	SCHOOL RATING** →	FAIR
------------------------	---	---------------	--------------------------	-------------

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-98.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75%-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

COMMENTS AND RATING EXPLANATION:

PAINT IS PEELING ON UPPER EAVES THROUGHOUT CAMPUS.

PART II: EVALUATION DETAIL

Date of Inspection: 07/29/20

School Name: SILVEYVILLE CHARTER SCHOOL

AREA	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
	GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUNDS/ SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES
ADMIN	OK	OK	OK	OK	OK	OK	OK	NA	NA	OK	OK	OK	OK	OK	OK
	COMMENTS:	(NO ENTRY DUE TO COVID-19 CONCERNS)													
NURSE	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK
	COMMENTS:	(NO ENTRY DUE TO COVID-19 CONCERNS) 7. ONE LIGHT DIFFUSER IS BROKEN.													
PRINCIPAL	OK	OK	OK	OK	OK	OK	OK	NA	NA	OK	OK	OK	OK	OK	OK
	COMMENTS:	(NO ENTRY DUE TO COVID-19 CONCERNS) 4. CEILING TILE IS BROKEN. CEILING TILE HAS A WATER STAIN. 7. OUTLET COVER IS BROKEN.													
DEAN OF STUDENTS	OK	OK	OK	OK	OK	OK	OK	NA	OK	OK	OK	OK	OK	OK	OK
	COMMENTS:	(NO ENTRY DUE TO COVID-19 CONCERNS) 4. FORMICA TRIM IS CHIPPING ON COUNTER TOP. 7. BOTH LIGHT DIFFUSERS ARE MISSING.													
COPY ROOM/ MDF	OK	OK	OK	D	OK	OK	D	NA	NA	OK	OK	OK	OK	OK	OK
	COMMENTS:	4. CEILING TILES ARE BROKEN. CEILING TILES HAVE WATER STAINS. CEILING TILES ARE MISSING. FLOOR TILES ARE BROKEN. 7. ONE LIGHT DIFFUSER HAS A WATER STAIN. OUTLET COVER IS MISSING.													
	OK	OK	OK	OK	OK	OK	OK	NA	NA	OK	OK	OK	OK	OK	OK
	COMMENTS:														
MENS REST ROOM	OK	OK	OK	OK	OK	OK	OK	OK	D	OK	OK	OK	OK	OK	OK
	COMMENTS:	9. FAUCET LEAKS AT HANDLE. FAUCET HANDLE IS DETERIORATING.													
WOMENS REST ROOM	OK	OK	OK	D	OK	OK	OK	OK	D	OK	OK	OK	OK	OK	OK
	COMMENTS:	4. LINOLEUM FLOORING IS CRACKING ALONG COVE BASE. 9. FAUCET HAS A LOW FLOW.													
1	OK	OK	OK	OK	OK	OK	OK	NA	D	OK	OK	OK	OK	OK	D
	COMMENTS:	9. DRINKING FOUNTAIN HAS A HIGH FLOW. 15. DRY ROT ON WINDOW FRAMES AND EAVES.													
2	OK	OK	OK	OK	OK	OK	D	NA	OK	OK	OK	OK	OK	OK	D
	COMMENTS:	7. PIECE OF ELECTRICAL CONDUIT IS MISSING EXPOSING LIVE WIRES. ELECTRICAL COVER IS BROKEN. 15. DRY ROT ON WINDOW FRAMES AND EAVES.													
3	OK	OK	OK	D	OK	OK	OK	NA	D	OK	OK	OK	OK	OK	OK
	COMMENTS:	4. CEILING TILES ARE LOOSE. 9. DRINKING FOUNTAIN IS LOOSE AT BASE.													
4	OK	OK	OK	D	OK	OK	OK	NA	OK	OK	OK	OK	OK	OK	D
	COMMENTS:	4. CEILING TILE IS BROKEN. CEILING TILES ARE LOOSE. 15. DRY ROT ON WINDOW FRAMES.													
CUSTODIAL	OK	OK	OK	D	OK	OK	OK	NA	OK	OK	D	OK	OK	OK	OK
	COMMENTS:														

PART II: EVALUATION DETAIL Date of Inspection: 07/29/20 School Name: SILVEYVILLE CHARTER SCHOOL

CATEGORY AREA	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
	GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES
CUSTODIAL	COMMENTS: 4. CEILING HAS A HOLE. 11. PAINT IS PEELING ON WALL.														
GIRLS REST ROOM	OK	OK	OK	OK	OK	OK	OK	OK	D	OK	OK	OK	OK	OK	OK
	COMMENTS: 9. SINK IS LOOSE FROM THE WALL.														
BOYS REST ROOM	OK	D	OK	OK	OK	OK	D	OK	D	OK	OK	OK	OK	OK	OK
	COMMENTS: 2. EXHAUST FAN IS NOT WORKING. 7. LIGHT DIFFUSER IS MISSING. 9. SINK CAPS ARE MISSING. SINK IS LOOSE FROM WALL.														
9	OK	OK	OK	OK	OK	OK	OK	NA	OK	OK	OK	OK	OK	OK	D
	COMMENTS: 15 DRY ROT ON WINDOW FRAMES. WINDOW IS BROKEN.														
8	OK	OK	OK	D	OK	OK	OK	NA	OK	OK	OK	OK	OK	OK	D
	COMMENTS: 4. CEILING TILE IS LOOSE. 15. DRY ROT ON WINDOW FRAMES.														
7	OK	OK	OK	OK	OK	OK	OK	NA	OK	OK	OK	D	OK	OK	OK
	COMMENTS: 12. DRY ROT ON EAVES.														
6	OK	OK	OK	OK	OK	OK	D	NA	D	OK	OK	OK	OK	D	OK
	COMMENTS: 7. ETHERNET COVER IS MISSING. 9. SINK CAP IS MISSING/LOOSE. 14. TRIP HAZARD AT ENTRY.														
5	OK	OK	OK	D	OK	OK	OK	NA	OK	OK	D	OK	OK	OK	OK
	COMMENTS: 4. CEILING TILES ARE LOOSE. 11. PAINT IS PEELING ON CEILING.														
21	OK	OK	OK	D	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK
	COMMENTS: 4. CEILING TILES ARE LOOSE. CEILING TILES HAVE HOLES.														
BOYS REST ROOM	OK	D	OK	D	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK
	COMMENTS: 2. EXHAUST FAN IS NOT WORKING. 4. WALL TILE IS BROKEN.														
CUSTODIAL	OK	OK	OK	OK	OK	OK	OK	NA	OK	OK	OK	OK	OK	OK	OK
	COMMENTS:														
GIRLS REST ROOM	OK	OK	OK	D	D	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK
	COMMENTS: 4. FLOOR TILE IS MISSING. 11. PAINT IS PEELING ON THE CEILING.														
20	OK	OK	OK	OK	OK	OK	OK	NA	OK	OK	OK	D	OK	OK	OK
	COMMENTS: 12. DRY ROT ON SIDING.														

PART II: EVALUATION DETAIL

Date of Inspection: 07/29/20

School Name: SILVEYVILLE CHARTER SCHOOL

AREA	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
	GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/S CHOOH GROUNDS	WINDOWS/ DOORS/ GATES/FENCES
23	OK	OK	OK	OK	OK	OK	OK	NA	OK	OK	OK	OK	OK	OK	OK
	COMMENTS:														
10	OK	OK	OK	OK	OK	OK	D	NA	OK	OK	OK	D	OK	D	OK
	COMMENTS: 7. ELECTRICAL CONDUIT END CAP IS MISSING. OUTLET COVER IS BROKEN. 12. DRY ROT ON EAVES. 14. TRIP HAZARD ON WALKWAY.														
11	OK	OK	OK	D	OK	OK	D	NA	OK	OK	OK	OK	D	OK	OK
	COMMENTS: 4. CEILING TILE HAS A WATER STAIN. CEILING TILE IS LOOSE. 7. OUTLET COVER IS LOOSE EXPOSING LIVE WIRES. 13. HOLES IN GUTTER.														
12	OK	OK	OK	D	OK	OK	OK	NA	OK	OK	D	OK	D	OK	D
	COMMENTS: 4. CEILING TILE IS LOOSE. 11. PAINT IS PEELING ON THE EAVES. 13. DRY ROT ON EAVES. 15. DRY ROT ON WINDOW FRAME.														
13	OK	OK	OK	D	OK	OK	OK	NA	OK	OK	OK	OK	OK	OK	OK
	COMMENTS: 4. CEILING TILES HAVE WATER STAINS. CEILING TILE IS MISSING. FLOOR TILES ARE BROKEN AT ENTRY.														
14	OK	OK	OK	OK	OK	OK	D	NA	OK	OK	D	OK	D	OK	OK
	COMMENTS: 7. ONE LIGHT PANEL IS OUT. 11. PAINT PEELING ON EAVES. 13. PIECE OF EAVES TRIM IS MISSING/BROKEN.														
18	OK	OK	OK	D	OK	OK	D	NA	OK	OK	OK	OK	D	OK	OK
	COMMENTS: 4. CEILING TILES HAVE WATER STAINS. 7. ELECTRICAL CONDUIT END CAP IS MISSING. 13. EAVES ARE WARPED (THROUGHOUT BUILDING).														
19	OK	OK	OK	D	OK	OK	OK	NA	OK	OK	OK	OK	D	OK	OK
	COMMENTS: 4. CEILING TILE IS LOOSE. CEILING TILE T-BAR IS MISSING. 13. EAVES TRIM IS MISSING.														
20	OK	OK	OK	D	OK	OK	D	NA	OK	OK	D	OK	OK	OK	OK
	COMMENTS: 4. CEILING TILE IS MISSING. CEILING TILE IS LOOSE. CEILING TILE T-BARS ARE MISSING AND LOOSE. 7. ONE LIGHT PANEL IS OUT. 11. PAINT IS PEELING ON EAVES.														
GIRLS REST ROOM	OK	OK	OK	D	OK	OK	D	D	D	OK	OK	OK	D	OK	OK
	COMMENTS: 4. SOAP DISPENSER TOP IS MISSING. 7. LIGHT DIFFUSER IS MISSING. 8. TOILET SEAT IS BROKEN. 9. EXTERIOR DRINKING FOUNTAIN HAS A HIGH FLOW. 13. EAVES TRIM IS LOOSE														
CUSTODIAL	OK	OK	OK	OK	OK	OK	OK	NA	NA	OK	OK	OK	OK	OK	OK
	COMMENTS:														
SCIENCE OFFICE	OK	OK	OK	OK	OK	OK	OK	NA	OK	OK	OK	OK	OK	OK	OK
	COMMENTS:														
BOYS REST	OK	OK	OK	OK	OK	OK	OK	OK	D	OK	D	OK	D	OK	D

PART II: EVALUATION DETAIL Date of Inspection: 07/29/20 School Name: SILVEYVILLE CHARTER SCHOOL

AREA	CATEGORY	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
		GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUNDS/ CHOOH GROUND	WINDOWS/ DOORS/ GATES/FENCES
	ROOM	COMMENTS: 9. EXTERIOR DRINKING FOUNTAIN HAS A HIGH FLOW. FAUCET HAS A CONSTANT DRIP. 11. PAINT IS PEELING ON CEILING. 13. HOLES IN EAVES. 15. THRESHOLD IS MISSING.														
17		OK	OK	OK	D	OK	OK	D	NA	OK	OK	OK	OK	OK	OK	OK
		COMMENTS: 4. CEILING TILE HAS A HOLE. 7. ETHERNET COVER IS LOOSE.														
16		OK	OK	OK	D	OK	OK	D	NA	D	OK	OK	OK	OK	OK	OK
		COMMENTS: 4. CEILING TILE IS MISSING. FLOOR TILES ARE LOOSE. 7. ELECTRICAL CONDUIT END CAP IS MISSING. 9. DRINKING FOUNTAIN HANDLE IS BROKEN.														
15		OK	OK	OK	OK	OK	OK	OK	NA	OK	OK	OK	OK	OK	OK	OK
		COMMENTS: (NO ENTRY DUE TO COVID-19 CONCERNS) 4. CEILING TILES ARE LOOSE. 7. ELECTRICAL COVER IS MISSING.														
27		OK	OK	OK	D	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK
		COMMENTS: 4. CEILING TILES HAVE WATER STAINS.														
36		OK	OK	OK	D	OK	OK	D	NA	OK	OK	D	D	OK	D	OK
		COMMENTS: 4. CARPET IS TORN. 7. ONE LIGHT DIFFUSER IS MISSING. 11. PAINT IS PEELING ON EAVES (RUSTED ALSO). 12. DRY ROT ON SIDING. 14. TRIP HAZARD ON WALKWAY. BENCH IS DAMAGED.														
35		OK	OK	OK	OK	OK	OK	D	NA	OK	OK	OK	D	OK	OK	D
		COMMENTS: 7. TWO OUTLET COVERS ARE MISSING. ELECTRICAL COVER IS MISSING. 12. DRY ROT ON SKIRTING AND RAMP SKIRTING. 15. WINDOW SCREENS ARE MISSING.														
34		OK	OK	OK	D	OK	OK	OK	NA	D	OK	D	OK	OK	OK	OK
		COMMENTS: 4. RUBBER MOLDING IS MISSING. 9. FAUCET HANDLE IS MISSING. 11. PAINT IS PEELING ON EAVES.														
33		OK	OK	OK	OK	OK	OK	OK	NA	OK	OK	D	OK	OK	OK	OK
		COMMENTS: 11. PAINT PEELING ON EAVES. PAINT IS PEELING ON RAMP RAILING. (USED AS STORAGE)														
32		OK	OK	OK	D	OK	OK	D	NA	OK	OK	D	D	OK	OK	OK
		COMMENTS: 4. CEILING TILES ARE MISSING. 7. MULTIPLE LIGHT PANELS ARE OUT. 11. PAINT IS PEELING ON EAVES. 12. DRY ROT ON RAMP SKIRTING. 15. DOOR IS RUSTED.														
31		OK	OK	OK	D	OK	OK	D	NA	OK	OK	OK	OK	OK	D	OK
		COMMENTS: 4. CARPET IS LIFTING. RUBBER MOLDING IS MISSING. 7. ONE LIGHT PANEL IS OUT. 14. TRIP HAZARD ON ASPHALT AT ENTRY. RAMP IS RUSTING.														
30		OK	OK	OK	D	OK	OK	OK	NA	NA	OK	OK	D	D	D	OK
		COMMENTS: 4. CARPET IS WORN AND TORN. 12. DRY ROT ON SIDING. 13. EAVES HAVE WATER DAMAGE (RUSTED). 14. TRIP HAZARD AT RAMP/ASPHALT SEAM.														
21		OK	OK	OK	D	OK	OK	OK	NA	NA	OK	OK	OK	OK	OK	OK
		COMMENTS: 4. FLOOR TILES HAVE HOLE AND ARE LIFTING. CARP ; TORN AND LIFTING.														

PART II: EVALUATION DETAIL Date of Inspection: 07/29/20 School Name: SILVEYVILLE CHARTER SCHOOL

AREA	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
	GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES
25	OK	OK	OK	D	OK	OK	D	OK	D	OK	OK	OK	OK	OK	OK
	COMMENTS:	4. FLOOR TILES HAVE HOLE AND ARE LIFTING. 7. ONE LIGHT PANEL IS OUT. 9. DRINKING FOUNTAINS HAVE NO FLOW.													
26	OK	OK	OK	OK	OK	OK	OK	NA	NA	OK	OK	OK	OK	OK	OK
	COMMENTS:														
29	OK	OK	OK	D	OK	OK	OK	NA	NA	OK	OK	OK	OK	OK	D
	COMMENTS:	4. CEILING TILES HAVE WATER STAINS. CEILING TILE IS BROKEN. CEILING TILE HAS A HOLE. 15. WINDOW SCREEN IS MISSING.													
37	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK
	COMMENTS:	NO LONGER EXISTS.													
STAFF REST ROOM (NEAR 4)	OK	OK	OK	D	OK	OK	OK	OK	D	OK	OK	OK	OK	OK	OK
	COMMENTS:	4. LINOLEUM IS PEELING NEAR TOILET. 9. FAUCET LEAKS AT HANDLE.													
MPR	OK	OK	OK	OK	OK	OK	D	OK	OK	OK	OK	OK	OK	OK	OK
	COMMENTS:	7. ONE LIGHT DIFFUSER IS MISSING.													
STAGE	OK	OK	OK	D	OK	OK	OK	NA	NA	OK	OK	OK	OK	OK	OK
	COMMENTS:	4. CEILING TILES ARE MISSING.													
KITCHEN	OK	OK	OK	OK	OK	OK	D	NA	OK	OK	OK	OK	OK	OK	OK
	COMMENTS:	7. OUTLET COVER IS BROKEN.													
PLAY COURTS	OK	NA	OK	NA	OK	OK	NA	NA	NA	NA	OK	NA	NA	OK	OK
	COMMENTS:														
PLAY FIELDS	OK	NA	OK	NA	OK	OK	NA	NA	NA	NA	OK	NA	NA	OK	OK
	COMMENTS:														
PLAY GROUNDS	OK	NA	OK	NA	OK	OK	NA	NA	NA	NA	OK	NA	NA	OK	OK
	COMMENTS:														
PARKING LOTS	OK	NA	OK	NA	OK	OK	NA	NA	NA	NA	OK	NA	NA	D	OK
	COMMENTS:	14. TRIP HAZARDS.													
STAFF LOUNGE/	OK	OK	OK	OK	OK	OK	OK	NA	NA	OK	OK	OK	OK	OK	OK

PART II: EVALUATION DETAIL Date of Inspection: 07/29/20 School Name: SILVEYVILLE CHARTER SCHOOL

CATEGORY AREA	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
	GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/S CHOO L GROUNDS	WINDOWS/ DOORS/ GATES/FENCES
62	COMMENTS														
SPEECH	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK
	COMMENTS														

Marks: **OK** = Good Repair; **D** = Deficiency; **X** = Extreme Deficiency; **NA** = Not Applicable
 Use additional Area Lines as necessary.

